



### In Situ Temperature Measurement Test Report

For

# SHENZHEN SUNPER OPTO CO.,LTD

(Brand Name: SUNPER)

5/F,BLOK C,SANMIN INDUSTRIAL PARK,SHIYAN STREET, BAO'AN DISTRICT,SHENZHEN 518108,GUANGDONG,CHINA

#### High-Bay Luminaires for Commercial and Industrial buildings

Model name(s): SP-HB-200WA

Representative (Tested) Model:SP-HB-200WA(4000K)

Model Different: All construction and rating are the same, except CCT

Test & Report By:

Sean Zhuo

Engineer: Sean Zhuo Date: Dec.10,2014

Review By:

Manager: Tommy Liang

Tommy Liang

Note: This report does not imply product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government.





### **Table of Contents**

1 Ge	neral	3
	1.1 Product Information	3
	1.2 Standards or methods	4
	1.3 Equipment list	
	2.1 Ambient Condition	4
	2.2 Temperature Stabilization	4
	2.3 Thermocouples	5
	2.4 Thermocouples contact	
	3.1 Data:	6
	3.3 Test Photo:	6









# 1 General

### 1.1 Product Information

rand Name	SUNPER				
lodel Number	SP-HB-200WA				
uminaire Type	High-Bay Luminaires for Commercial and Industrial				
	buildings				
ominal Power	200 W				
ated Initial Lamp Lumen					
eclared CCT	4000K,4500K,5000K,5700K				
Luminaire Aperture] [Size]					
ED Manufacturer	CREE				
ED Model	Xlamp XT-E				
ample Receipt Date	Dec.08,2014				
ample Number	141129-5				
ample Number	141129-5				

#### **Photo**







Laboratory: Standard-Tech Co. Ltd Testing Center **NVLAP CODE: 201011-0** 





#### 1.2 Standards or methods

The following standards are partly or totally used or referenced for test:

No.	Name
ANSI/UL 1598:2008	Luminaires

#### 1.3 Equipment list

Equipment ID	<b>Equipment Name</b>	Last Calibration Date	Next Calibration Date		
PF210	Power Meter	2014-07-01	2015-06-30		
ST-R-181A	Temperature Tester	2014-07-01	2015-06-30		

# 2 Test conducted and method

#### 2.1 Ambient Condition

Test was conducted in an ambient temperature of  $25\pm5$  °C. Ambient temperature variations above or below 25 °C was subtracted from or added to temperatures recorded at points on the luminaire.

The ambient temperature was measured by a thermocouple which was immersed in 15ml of mineral oil in a glass container.

#### 2.2 Temperature Stabilization

Temperatures were measured after they have stabilized when the test has been running for a minimum of 7.5 hours, or the test has been running for a minimum of 3 hours and three successive reading taken at 15 minutes intervals are with  $1^{\circ}$ C of another and are not rising.





### 2.3 Thermocouples

Type J thermocouple was used for temperature measurement. The thermocouple was 0.05mm2(30AWG), and complied with the requirements specified in ASTM MNL 12 and limits of error specified in NIST ITS 90 and ISA MC96.1.

# 2.4 Thermocouples contact

Thermocouples were in contact with the TMP LED location described in LM-80 test report. In order to gain the maximum temperature, if appropriate, more than one thermocouple were contact in these locations. For details information, please refer to clause 3.3 for the photo of thermocouple contact.





# 3 Test Results


Test date		2014-12-09	Test Ambient 25.1 ℃			
Samp	le No.		LED Package Model			
1411	29-5		Xlamp XT-E			
LED driver of Each Lamp Output voltage			e V	Measured LED w	orking current (Max.) mA	
1	1 33.4				903.2	

#### **3.1 Data:**

Input	Vol.	120.1 V	/ Input Curr	ut Current 1.7		'351A	Input Wattage		l 206.7W l		Temperature abilization time:	500 min
No.	lo. Temperature (°C)		No.	o. Tempera		ture (°C	ure (°C) No.		Tempera	ture (°C)		
	Measured Corrected at 25°C			Moscured		Corre	ected		Magazza	Corrected		
			at 25°C			Measured		at 2	:5°C		Measured	at 25°C
1	78.8		78.7	3		78.7		78.6		5	80.2	80.1
2	79.0		78.9	4		79.2		79.1		6	79.0	78.9
The highest in-situ measured temperature LED is 80.1°C												

#### 3.2 Test Photo:

Ts Position:




Laboratory: Standard-Tech Co. Ltd Testing Center NVLAP CODE: 201011-0








Thermocouple Location on Temperature Measurement Point (TMP):





Laboratory: Standard-Tech Co. Ltd Testing Center NVLAP CODE: 201011-0





Table 1: Report at each LM-80 Test Condition							
Description of LED Light (manufacturer, catalog num	model,	CREE,Xlamp XT-E					
Test Condition 1 - 55°C	Case Temp	Test Condition 2 - 85°C	Case Temp	Test Condition 3 - 105°C Case Temp			
Sample size	25	Sample size	25	Sample size	25		
Number of failures	0	Number of failures	0	Number of failures	0		
DUT drive current used in the test (mA)		DUT drive current used in the test (mA)	1000	DUT drive current used in the test (mA)	1000		
Test duration (hours)	10,000	Test duration (hours)	10,000	Test duration (hours)	10,000		
Test duration used for projection (hour to hour)	5,040 - 11,592	Test duration used for projection (hour to hour)	5,040 - 11,592	Test duration used for projection (hour to hour)	5,040 - 11,592		
Tested case temperature (°C)	55	Tested case temperature (°C)	85	Tested case temperature (°C)	105		
α	4.720E-07	α	6.895E-07	α	-2.478E-07		
В	0.990	В	0.989	В	0.956		
Calculated L70(10k) (hours)	735,000	Calculated L70(10k) (hours)	501,000	Calculated L70(10k) (hours)	(1,258,000)		
Reported L70(10k) (hours) >60000		Reported L70(10k) (hours)	>60000	Reported L70(10k) (hours)	(1,258,000)		

	e 2: Interpolation Report ed on <i>in-situ</i> temperature entered)
T <sub>s,1</sub> (°C)	55.00
T <sub>s,1</sub> (K)	328.15
$\alpha_1$	4.720E-07
B <sub>1</sub>	0.990
T <sub>s,2</sub> (°C)	85.00
T <sub>s,2</sub> (K)	358.15
$\alpha_2$	6.895E-07
B <sub>2</sub>	0.989
E <sub>a</sub> /k <sub>b</sub>	1.48E+03
A	4.349E-05
B <sub>0</sub>	0.989
T <sub>s,i</sub> (°C)	80.70
T <sub>s,i</sub> (K)	353.85
$\alpha_{i}$	6.556E-07
Projected L70(10k) at 80.7°C (hours)	528,000
Reported L70(10k) at 80.7°C (hours)	>60000

\*\*\*\*\* END OF THE TEST REPORT\*\*\*\*\*

Laboratory: Standard-Tech Co. Ltd Testing Center NVLAP CODE: 201011-0

Report Format Number STD/QR4918-A/0